

# 3M

## Diffusional Monitor Analysis Report



Analytical Service  
3M Personal Safety Division  
Telephone: 800-243-4630

EMSL Analytical, Inc.  
1830 Elm St. SE  
Minneapolis, MN 55414



Report Number:	1800029	Page 1 of 2
No. of Monitors:	6	Test Method Used: 3M 3550
Analysis Performed:	1/16/2018	Report Date: 1/17/2018
Analyzed By:	RSS	

Client: Customed, Inc.  
Hector W. Agosto  
Calle Igualdad #7  
Fajardo, PR 00738

Project Manager  
\* 3M Analysis Services provided by  
EMSL Analytical, Inc.  
(AIHA-LAP Laboratory ID 101103)

User Identification	Monitor Code	Sampling Date	Sampling Time	Weight	Concentration		Footnotes
		Compound(s)		Micrograms	mg/m3	PPM	
Joel Soto	VP3535	12/30/17	480 min.				
		Ethylene Oxide		<2.98	<0.126	<0.0697	
Juan C Pacheco	VP3614	12/30/17	480 min.				
		Ethylene Oxide		<2.98	<0.126	<0.0697	
Control	VP3289	12/30/17					
		Ethylene Oxide		<3.00	---	---	
Chamber Room	VP3794	12/30/17	480 min.				
		Ethylene Oxide		<2.98	<0.126	<0.0697	
ETO Room	VP3518	12/30/17	480 min.				
		Ethylene Oxide		<2.98	<0.126	<0.0697	
Bed Reactor	VP3476	12/30/17	480 min.				
		Ethylene Oxide		4.57	0.193	0.107	

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the laboratory, unless specifically indicated. The final results are not field blank corrected, unless otherwise noted. The laboratory is not responsible for final results calculated using sampling times that have been provided by non-laboratory personnel. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

#### Footnotes:

< = This analyte not detected at or above the reported limit.